ess :	perty ID:	2995		<u> </u>			SOINI	S Documen
	: 4312	YORK S	TREET			3-18-0		
ner: pector/Assessor:					Telephone CO Certific	<u>n</u>	1035147	
Plan			<u> </u>		00 00.4.10	44011 #1 1200		EXPOSED BA
,	••							
		•						NHITE TRIN
	•			~ · · · · · ·		- ** · · · · · · · · · · · · · · · · · ·	• •	
					Uau	ur w rind	TV-15 5CH	EDVLED TO
		•			BE	DEMOLISH	ED.	
								
				į				
						•		
) ,,						
		# 2	2995					
				}				
				l				
				1				
		'		İ				-
		1		<u></u>	1			
				1				
				SHED				
			<u>.</u> .		}			
	}				•			
١.								
<u>_/</u>	<u> </u>							
<u> </u>	V		YORK ST	ſ				
	<u> </u>	Exten		1		Doo	rs/Trim	
	Material	Exten Area	YORK ST ior Walls Peel/Chip	XRF (Lead)	Material	Door Area	s/Trim Peel/Chip	XRF (Lead)
th			ior Walls		Material			XRF (Lead)
th th			ior Walls		Material			XRF (Lead)
th th			ior Walls		Material			XRF (Lead)
th th			ior Walls		Material			XRF (Lead)
th th	Material	Area	ior Walls Peel/Chip	XRF (Lead)	Material	Area	Peel/Chip	XRF (Lead)
th th	Material	Area Window Tri	ior Walls Peel/Chip	XRF (Lead)		Area Patios/De	Peel/Chip cks/Porches	
th th tt st	Material	Area	ior Walls Peel/Chip	XRF (Lead)	Material Material	Area	Peel/Chip	XRF (Lead)
th th tt	Material	Area Window Tri	ior Walls Peel/Chip	XRF (Lead)		Area Patios/De	Peel/Chip cks/Porches	
th th tt st	Material	Area Window Tri	ior Walls Peel/Chip	XRF (Lead)		Area Patios/De	Peel/Chip cks/Porches	
th th t st	Material	Area Window Tri	ior Walls Peel/Chip	XRF (Lead)		Area Patios/De	Peel/Chip cks/Porches	
th th t st	Material Material	Area Window Trir	ior Walls Peel/Chip	XRF (Lead)		Area Patios/De	Peel/Chip cks/Porches	
th th t st	Material Material	Window Trin	ior Walls Peel/Chip m/Fascia/Soffi	t XRF (Lead)	Material	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)
th th t st	Material Material WOOD	Area Window Trin Area	ior Walls Peel/Chip m/Fascia/Soffii Peel/Chip	t XRF (Lead)	Material	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)
th	Material Material WOOD	Window Trin Area etal Trim/Gut Area	ior Walls Peel/Chip m/Fascia/Soffi	t XRF (Lead)	Material	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)
th th t st	Material Material WOOD	Area Window Trin Area	ior Walls Peel/Chip m/Fascia/Soffii Peel/Chip tters/Downspor	XRF (Lead) XRF (Lead) XRF (Lead) XRF (Lead)	Material Naterial	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)
th that the the that the theta the the that the theta the the that the theta the	Material Material WOOD	Window Trin Area etal Trim/Gut Area	ior Walls Peel/Chip m/Fascia/Soffii Peel/Chip tters/Downspor	XRF (Lead) XRF (Lead) XRF (Lead) XRF (Lead)	Material Naterial	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)
th th t st t	Material Material WOOD	Window Trin Area etal Trim/Gut Area	ior Walls Peel/Chip m/Fascia/Soffii Peel/Chip tters/Downspor	XRF (Lead) XRF (Lead) XRF (Lead) XRF (Lead)	Material Naterial	Patios/De Area	Peel/Chip cks/Porches Peel/Chip	XRF (Lead)

- -

Time	Site	Component	Substrate	Side	Condition	Color	Floor	Room	Results	Depth Inde	PbC	PbC Error
8/18/2005 14:24	2995	DOOR TRIM	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	5.1	0.03	0.06
8/18/2005 14:24	2995	WINDOW FRAME	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Positive	5.38	7.1	0.7
8/18/2005 14:25	2995	COLUMN	WOOD	WEST	CRACKED	WHITE	FIRST	OUTSIDE	Negative	1	0	0.02
8/18/2005 14:27	2995	DOOR FRAME	WOOD	WEST	CRACKED	BROWN	FIRST	SHED	Negative	3.06	0.01	0.02
8/18/2005 14:28	2995	EXT. WALL	WOOD	WEST	CRACKED	TAN	FIRST	SHED	Negative	4.53	0.02	0.04
8/18/2005 14:29	2995	HAND RAIL	WOOD	NORTH	CRACKED	WHITE	FIRST	OUTSIDE	Negative	1	0	0.02
						•						
						<u> </u>						
				ļ				<u> </u>				
	<u> </u>	! !										
					1							
		<u> </u>	<u> </u>									
	<u> </u>											
Note: Readings	are in n	ng/cm²										
Painted surface	s not te	sted were assessed	d to be in "i	ntact" cor	idition at tim	e of site v	isit.					

Color Photo(s)

The following pages contain color that does not appear in the scanned images.

To view the actual images, contact the Region VIII Records Center at (303) 312-6473.

Property ID # 2995 / 4312 York Street



House is vacant & is scheduled to be demolished